Locality Briefing
30/06/2023

Balfour Beatty · **Herefordshire Council**
Working for Herefordshire

Ross Town Locality

Harry.Bradbury@balfourbeatty.com

07542 865623

Ross Town Locality Wards

Kerne Bridge, Penyard,
Ross North, East & West

June Fast Facts

Enquiries: 105
Defects Raised: 35
Emergency Jobs: 9
Self-Completed Jobs: 21

Weekly Update

Hi everyone, this week I have successfully completed my 2 day operational playground inspectors course, allowing me to assess the playground equipment within Ross on Wye that BBLP/HC are responsible for. On the days where I have been in, I have been attending enquiries, emergencies and completing jobs on the network.

Next Week :

Next week I am on annual leave – enquiries will be attended to upon my return. Any emails will also be responded to upon my return.

Self-Generated Works

When I am out and about on the network and I have the capacity, I undertake simple maintenance jobs providing it is safe to do so and requires no traffic Management.

Cutters Lane, Goodrich Pothole repaired by LS	**B4224 A40 to Bromsash** Vegetation around signage cut back by LS

Balfour Beatty Volunteer Days

Each year Balfour Beatty staff are entitled to take 2 days to complete volunteer work! This can be anything from litter picking with litter picking groups, to supporting vegetation clearing in community areas. Generally, our volunteer days are used where we can best utilise our skills (highways/public realm based tasks).
An Example - One of my colleagues assists the Burghill in Bloom team each year with vegetation control, planting etc

If you have an event coming up where you are looking for volunteers to assist, drop me an email and I can review and respond! I can also try round up some other volunteers to assist!

Completed Jobs this week by ward.
(Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	Completed
Kerne Bridge	The Doward from Hawthorn Cottage	Weed Treatment	1
Kerne Bridge	B4229 from Old Forge Bridge B4234 from New House Farm	LS Self Completed Works (sign Cleaning)	1 1
Kerne Bridge	Cherry Tree Lane Church Howle Road Church Road Cutters Lane	Pothole repairs by Velocity Patching machine	Carriageways were driven between start and end points by the Velocity Patching machine and all defects appropriate filled.
Ross West	Brookend Street	Barrier Collection	1
Ross West	C1274 Roman Way	LS Self Completed Works (sign cleaning)	1
Ross West	Royal Parade	Litter Picking	1
Ross West	Frome Valley Way	Fly Tip Collection	1
Ross West	Ashfield Crescent Archenfield Road Walford Road	Gully Clearing	1 1 1
Ross North	Ledbury Road	Vegetation cut back	1
Ross North	Homs Road Brampton Road	Overflowing Litter bins	1 1
Ross North	Brampton Road	Vegetation Cut back	1
Penyard	C1281 Aston Crews B4221 from Revells Lane C1283 from C1280 A40	Gully Cearing	2 2 1 1
Penyard	B4221 from Revells Lane	Litter Picking	1
Penyard	B4224 from Fording Lane	LS Self Completed Works (Vegetation cut back)	1
Ross East	Waterside Footway Merrivale Crescent Ross on Wye Cycle Way	Empty Litter Bin	1 1 1
Ross East	A40 Hilldersley	Gully Clearing	5