Locality Briefing 05/04/2024

Location: C1274 Roman Way

Before

Type of repair: Temp TM removed

After

Balfour Beatty

Herefordshire Council

Working for Herefordshire

Ross Tow	n Locali	ty	All defects on the network need to be reported through the correct channels	
	Covering the wards of		For General Enquiries: Online (general non-emergency enquiries): Report problems on the road – Herefordshire Council	
Upcoming Leave: N/A	Ross North Ross West Ross East Penyard Kerne Bridge		FixMyStreet Home - report app (herefordshire.gov.uk) 24/7 Phone number: 01432 261800 To Check progress on a defect: Pothole and road defect progress map – Herefordshire Counci To view current and upcoming roadworks https://one.network/	
April To Date Facts 🚿			Locality Weekly Update I hope everyone had an enjoyable bank holiday weekend! This week I have	
Enquiries Raised to date for LS		47	completed the statutory A & B road inspection, attended some parish meetings and attended a number of enquiries and emergencies in the locality Next Week Mon-Tues – Enquiries	
Defects Raised in Locality		48		
Emergency Defects Raised		3		
Self Completed Jobs by LS		11		
			Wed-Thurs – Statutory Inspections Fri – Ward member meeting & Enquiries	
Self Completed Works				
An Example of some of the works completed by myself this week.			Second//mnortent/nfo	

Seasonal/Important Info

We continue to experience torrential downpours across the county. During these events, please report any defects you see on the network using the above methods. If you believe something is an emergency or requires attendance ASAP, please call the 24/7 phone number to speak to someone in our office.

During these events we often stand down teams to assist with signage deployment and other emergencies on the network.

Completed Defects this week by ward. (Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	No. Completed
Ross North	Brampton Road	Flood Signage required	1
Ross North	Ross Road	Gully Clearing	1
Ross East	A40 Hilldersley	Debris removal	1
Ross East	Chase Side Gloucester Road	LS Self Completed Work (signage collection)	2
Ross East	Roman Way Play area	Gate Repair	1
Ross East	Alton Road	Pothole Repairs	1 x emergency
Ross West	C1274 Roman Way	LS Self Completed Work (signage collection)	1
Ross West	Beech Close	Play Area Repair	2
Kerne Bridge	Tuck Mill Lane C1250 A4137	Pothole repairs	1 1 2
Penyard	C1281 Aston Crews	Gully Repair	1
Penyard	A40 Ryeford Farm	Fly Tip Collection	1
Penyard	Rock Farm Lane C1281 Aston Crews Warren Lane	Gully Clearing	2 6 1
Penyard	B4221	Litter pick collection	1
Penyard	Cut Throat Lane Springetts Lane Bartwood Lane C1281 Aston Crews B4224 C1275 C1277 Hope Mansel Lane	Pothole Repairs	2 8 2 2 17 1 1 2