Locality Briefing

15/03/2024

Balfour Beatty



Working for Herefordshire

Ross Town Locality



N/A

Covering the wards of

Ross North Ross West Ross East Penyard Kerne Bridge All defects on the network need to be reported through the correct channels For General Enquiries:

Online (general non-emergency enquiries):

Report problems on the road – Herefordshire Council **FixMyStreet**

Home - report app (herefordshire.gov.uk)

24/7 Phone number: 01432 261800

To Check progress on a defect:

Pothole and road defect progress map - Herefordshire Council

To view current and upcoming roadworks https://one.network/





Enquiries Raised to date for LS

Defects Raised in Locality

Emergency Defects Raised

Self Completed Jobs by LS



49

71

4

8

Self Completed Works

An Example of some of the works completed by myself this week.

Location: A40/Old Tannery Way



Type of repair: Fly posting removal

Before After





Locality Weekly Update

This week has been a short week for me with a couple of days annual leave in the mix. I have completed the monthly locality C road inspection and attended a number of enquiries and emergencies across the area. I have also helped out in a neighbouring locality where a colleague is currently away.

Next Week

Monday - Monthly Town walked inspection & monthly playgrounds inspection Friday - Monthly team meeting



Seasonal/Important Info

We continue to experience torrential downpours across the county. During these events, please report any defects you see on the network using the above methods. If you believe something is an emergency or requires attendance ASAP, please call the 24/7 phone number to speak to someone in our office.

During these events we often stand down teams to assist with signage deployment and other emergencies on the network.

Completed Defects this week by ward. (Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	No. Completed
Ross North	Old Tannery Way	LS Self Completed (Flyposting Removed)	1
Ross North	Ross Road A449	Fly Tip Collection	1
Ross North	A449	Litter Picking	1
Ross North	Station Approach	Footway trip repairs	1
Ross East	Sussex Avenue Roman Way Cantilupe Road	Community litter pick collections	1 1 1
Penyard	B4221	Hand sweeping	1
Penyard	B4221	Community litter pick collections	1
Penyard	B4222	Grit bin re-fill	1
Penyard	B4221 B4224 C1287	Pothole Repairs	18 1 1
Ross West	Palmerston Road	TM set up	1
Ross West	Frome Valley Way	Ad-hoc Litter bin emptying	1
Ross West	Brookend Street Church Street	Fly Tip Collection	1 1
Ross West	New Street	Footway Trip repairs	1
Kerne Bridge	The Deane Road	Grit bin refill	1