

Ross Town Locality



Upcoming Leave:
N/A

Covering the wards of

Ross North
Ross West
Ross East
Penyard
Kerne Bridge

All defects on the network need to be reported through the correct channels

For General Enquiries:

Online (general non-emergency enquiries):

[Report problems on the road – Herefordshire Council](#)

[FixMyStreet](#)

[Home - report app \(herefordshire.gov.uk\)](#)

24/7 Phone number:

01432 261800

To Check progress on a defect:

[Pothole and road defect progress map – Herefordshire Council](#)

To view current and upcoming roadworks

<https://one.network/>



To Date Facts



Enquiries Raised to date for LS	165
Defects Raised in Locality	180
Emergency Defects Raised	23
Self Completed Jobs by LS	17

Self Completed Works

An Example of some of the works completed by myself this week.

Location: Revells Lane, Linton

Type of repair: Cleared debris and mud that was covering gully



Before

After



Locality Weekly Update

This week I spent most of the week assisting my colleague in the golden valley with an annual inspection. When I returned to the area I cleared through most of my enquiries and had a real drive on getting some self completed works in! As it's the end of the month I also spent some time re-checking ongoing issues around the locality.

Next Week

March!!! The monthly inspections of A/B/C roads start again as well as a quarterly inspection of Accident sites in the area.



Seasonal/Important Info

We continue to experience torrential downpours across the county. During these events, please report any defects you see on the network using the above methods. If you believe something is an emergency or requires attendance ASAP, please call the 24/7 phone number to speak to someone in our office.

During these events we often stand down teams to assist with signage deployment and other emergencies on the network.

Completed Defects this week by ward. (Completed between last Wednesday and 23:59hrs this Wednesday)			
Ward	Location	Job Type	No. Completed
Ross North	Brampton Road	TM Adjustment	1
Ross North	Ledbury Road	Fly Tip Collection	1
Ross North	Ledbury Road	Street Sweeping	1
Ross North	Ledbury Road	Pothole repair	1
Ross North	Station Approach	Footway Patching	1
Ross East	Cantilupe Road	Hazardous Waste Removal	1
Ross East	Woodview Lane	Pothole Repairs	4
	Alton Street		8
	Merrivale Lane		4
	Alton Road		3
	Ryefield Road		1
	Merrivale Road		1
Penyard	Cut Throat Lane	TM Installation	1
Penyard	A40, Lea	TM Adjustment	1
Penyard	A40, Lea	Pothole Repairs	1
	Pontshill Marsh Rd		11
	B4224		4
	C1275		7
	C1281		1
	B4221		4
	B4222		1
Kerne Bridge	Well Vale Lane	Emergency tree works	1
Kerne Bridge	Well Vale Lane	LS Self Completed Works Fallen Tree Removal	1
Kerne Bridge	Leys Hill Road	Verge Pull back	1
Kerne Bridge	B4234	Pothole repairs	1
	A4137		2
	C1259 Goodrich		4
	C1260		2
	C1275		2
	Leys Hill Road		1
Ross West	Archenfield Road	Emergency TM Set up	1

Completed Jobs this week by ward.

(Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	No. Completed
Ross West	Palmerston Road	LS Self Completed Works Emergency TM Set up	1
Ross West	Kennedy Place	Broken Glass removal	1
Ross West	Walford Road Over Ross Street Greytree Road	Pothole repairs	10 2 1

Some more examples of LS Self completed works from this week

Location: B4234, Bishopswood

Type of repair: Sign Cleaning

Before



After



Location: C1287, Gorsley

Type of repair: Sign Cleaning

Before



After



Location: Well Vale Lane

Type of repair: Fallen Tree Removal

Before



After



Location: B4222 Aston Crews

Type of repair: Sign Cleaned

Before



After

