# **Locality Briefing**

Week Ending 02/08/2024



**Working for Herefordshire** 

## **Ross Town Locality**



**Upcoming Leave:** None

Covering the wards of

Ross North **Ross West** Ross East Penyard Kerne Bridge All defects on the network need to be reported through the correct channels For General Enquiries:

Online (general non-emergency enquiries):

Report problems on the road – Herefordshire Council **FixMyStreet** 

Home - report app (herefordshire.gov.uk)

24/7 Phone number: 01432 261800

To Check progress on a defect:

Pothole and road defect progress map – Herefordshire Council

To view current and upcoming roadworks https://one.network/



## **July Facts**



**Enquiries Raised for LS** 

**Defects Raised in Locality** 58

**Emergency Defects Raised** 

2

111

Self Completed Jobs by LS

3

### Self Completed Works

An Example of some of the works completed by myself this week.

Location: C1274 Roman Way

Type of repair: 30mph terminal uncovered

### **Before**





## **Locality Weekly Update**

Hi Everyone, this week I have worked through some of the enquiries that have built up whilst I was annual leave. I have also completed the monthly walked inspection and the monthly playground inspections.

### Next Week Enquiries.



## Seasonal/Important Info

Herefordshire council have recently published a new policy on advertising signage that is placed on the highway.

As we enter the summer months, I know many parishes will be holding events. If you plan to put any signage out, please make sure you have read the below document.

Any signage on the network that does not meet the criteria will be removed by a Locality steward to ensure the safety of highway users is maintained.

The document can be viewed here -Issue details - Tourist and Temporary Event Signage Review - Herefordshire Council (see app.3 for specifications)

Completed Defects this week by ward. (Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	No. Completed
Ross West	Church Close	Lining Works	1
Ross West	Brookend Street	Footway ironwork repair	1
Ross West	Broad Street	Tactile paving repairs	1
Penyard	A40 Lea	Sign Repair	1
Kerne Bridge	B4229	Post replacement	1
Kerne Bridge	B4234	NSL sign replacement	1