# **Locality Briefing**

Week Ending 20/09/2024



**Working for Herefordshire** 

## **Ross Town Locality**



**Upcoming Leave:** None

Covering the wards of

Ross North **Ross West** Ross East Penyard Kerne Bridge All defects on the network need to be reported through the correct channels For General Enquiries:

Online (general non-emergency enquiries):

Report problems on the road - Herefordshire Council **FixMyStreet** 

Home - report app (herefordshire.gov.uk)

24/7 Phone number: 01432 261800

To Check progress on a defect:

Pothole and road defect progress map - Herefordshire Council To view current and upcoming roadworks

https://one.network/





**Enquiries Raised for LS** 

**Defects Raised in Locality Emergency Defects Raised** 

0

49

28

Self Completed Jobs by LS

1

### **Self Completed Works**

An Example of some of the works completed by myself this week.

Location: C1280 Weston Under Penyard

Type of repair: Signage collected

**Before** 

After





### **Locality Weekly Update**

Hi Everyone, you didn't miss the briefing last week, unfortunately I was unwell so one was not sent! This week I have has been busy, I have completed a high number of enquiries, completed the C and U monthly inspection as well as a site visit with a ward member and a meeting with a parish council.

#### Next Week



Monthly Walked inspection. Monthly Playgrounds inspection.

## Seasonal/Important Info

Our yearly cyclical programme of grit bin refilling has started!

This is expected to take a number of weeks to complete and you will see from the weekly briefing a high number have already been completed.

Across the county we have approx. 5000 grit bins to fill!

To allow us time to complete the programme, please avoid reporting any empty ones until the programme has clearly finished.

Our teams will also check for any damage.

Completed Defects this week by ward. (Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	No. Completed
Kerne Bridge	A4137 from A40	Visibility splay grass cut	1
Kerne Bridge	B4234 C1259	Pothole repairs	5 2
Penyard	C1280	LS Self Completed Works (Signage collections)	1
Penyard	C1281	Fly Tip Collection	1
Penyard	C1283 Springetts Lane	Gully Clearing	3 2
Penyard	B4221	Fly Tip Collection	1
Penyard	A40	Visibility Splay Grass Cut	1
Penyard	Hope Mansel Lane The Streete	Pothole repairs	1 1
Ross East	Town Trail	Fallen Tree Removal	1
Ross East	A40	Visibility Splay Grass Cut	1
Ross East	Henry Street Alton Street Merrivale Lane	Pothole Repairs	1 1 3
Ross North	Brampton Road	Vegetation Control	2